


Hygrometer user manual

Product diagram



Product specifications

1. Temperature measurement range: $-20^{\circ}\text{C} \sim 60^{\circ}\text{C}$ ($-4^{\circ}\text{F} \sim 140^{\circ}\text{F}$)
2. Temperature measurement accuracy: $\pm 1^{\circ}\text{C}$
3. Temperature resolution: 0.1
4. Humidity range: 20%-99%
5. Humidity measurement accuracy: $\pm 5\%$
6. Humidity resolution: 1%
7. Power supply: 3V CR2032*1

Product functions

1. Mounting mode: Double Side Tape / Powerful magnet
2. Temperature display
3. Humidity display