

Thermo-hygrometer user manual

KD-40

Product specifications

Temperature measurement range: $-20^{\circ}\text{C} \sim +60^{\circ}\text{C}$ ($-4^{\circ}\text{F} \sim +140^{\circ}\text{F}$)

Temperature measurement accuracy: $\pm 1^{\circ}\text{C}$ (1.8°F)


Temperature resolution: 0.1

Humidity measurement range: 20%RH-99%RH

Humidity measurement accuracy: $\pm 5\%\text{RH}$

Humidity resolution: 1%


Power supply: CR2032



Basic functions

1. Mounting mode: Double side tape / Holder
2. Temperature display
3. Humidity display
4. Comfort indicator
5. $^{\circ}\text{C}/^{\circ}\text{F}$ switch

Operation method



1. Press and hold the key for 1.5 seconds to turn on;
2. Double click the key to switch the temperature unit to $^{\circ}\text{C}/^{\circ}\text{F}$;
3. Press and hold the key for 1.5 seconds to power off;

Comfort Indicator



Comfortable



Normal



Uncomfortable

Humidity \ Temperature	< 40%	40%-74%	> 74%
< 22°C			
22°C-28°C			
> 28°C			