

Thermo-hygrometer user manual

KD-50

Product specifications

Temperature measurement range: -20°C ~+60°C (-4°F~+140°F)

Temperature measurement accuracy: ±1°C (1.8°F)


Temperature resolution: 0.1

Humidity measurement range: 20%RH-99%RH

Humidity measurement accuracy: ±5%RH

Humidity resolution: 1%

Power supply: CR2032



Basic functions


Max/Min value memory function

Temperature display / Humidity display

°C/°F temperature switch display

Comfort indicator

Operation method



Comfort Indicator



Comfortable



Normal



Uncomfortable

Humidity \ Temperature	< 40%	40%-74%	> 74%
<22°C			
22°C-28°C			
> 28°C			