

Thermo-hygrometer user manual

KD-60

Product specifications

Temperature measurement range: $-20^{\circ}\text{C} \sim +60^{\circ}\text{C}$ ($-4^{\circ}\text{F} \sim +140^{\circ}\text{F}$)

Temperature measurement accuracy: $\pm 1^{\circ}\text{C}$ (1.8°F)


Temperature resolution: 0.1

Humidity measurement range: 20%RH-99%RH

Humidity measurement accuracy: $\pm 5\%\text{RH}$

Humidity resolution: 1%

Power supply: CR2032



Basic functions

Max/Min value memory function

Temperature display / Humidity display


$^{\circ}\text{C}/^{\circ}\text{F}$ temperature switch display

Comfort indicator

Operation method



Long press the button for 1.5 seconds to power on/ power off, Double click to select the temperature unit: $^{\circ}\text{C}$ / $^{\circ}\text{F}$



Short press to check the MAX/MIN temperature/ humidity, short press again to exit (no operation in 5 seconds, automatically exit)

Long press the button for 1.5 seconds to clear stored MAX/MIN data

Open the stand, the product can stand on the table.

Comfort Indicator



Comfortable



Normal



Uncomfortable

Humidity \ Temperature	Humidity		
	< 40%	40%-74%	> 74%
< 22°C			
22°C-28°C			
> 28°C			