


Product specifications


Temperature measurement range: -20℃ ~+60℃ (-4°F ~+140°F)
Temperature measurement accuracy: ±1℃ (1.8°F)
Temperature resolution: 0.1
Humidity measurement range: 20%RH-99%RH
Humidity measurement accuracy: ±5%RH
Humidity resolution: 1%
Power supply: 1.5V AAA × 2




Basic functions

- ◆ Temperature / Humidity display
- ◆ °C/°F temperature switch
- ◆ MAX & MIN Records
- ◆ Comfort indicator
- ◆ Backlit display
- ◆ Time/Calendar/Alarm clock

Operation method



- ◆Click (①) key to switch between Time and Alarm
- ◆Hold (①) key for 2 seconds to Time setting mode
- ◆Hold (②) key for 2 seconds to select the temperature unit:℃ or °F
- ◆Click (③) key to check MAX/MIN Temperature & Humidity,in this interface, hold (③) key for 2 seconds to delete memory
- ◆Click (①②③) 3 buttons at the same time to power off
- ◆Touch the touch-sensitive button () at the top to turn on the backlight, and shut down automatically in 5 seconds



Open the stand ,the hygrometer can be stand on the table.

Slide down to open the battery cover

Time setting mode

- Hold (①) key for 2 seconds to Time setting mode,Click (②③) key to select 12/24HR
- Click (①) key to next step, Click (②) to add the date and hold the key to speed up setting, Click (③) to reduce the date and hold the key to speed up setting
- After setting,Click (①) to confirm and quit
- The Sequence is “12/24HR” - “Time” - “Date” - “Quit”
- In setting mode,without any operation about 5 seconds will return back to time mode

Alarm setting mode

- In time mode,Click (①) key to switch to alarm mode,Click (②③) to select alarm pattern 5/6/7/off (5 means alarm on Monday to Friday,6/7 means Monday to Saturday and Sunday, means alarm off)
- In alarm pattern 5/6/7 mode,hold (①) key for 2 seconds to alarm setting mode,the sequence is “Hour” - “Minute” - “Quit”
- Click (②) to add the time and hold the key to speed up setting
- Click (③) to reduce the time and hold the key to speed up setting

Comfort Indicator



Humidity \ Temperature	Humidity		
	< 40%	40%-74%	> 74%
<22℃			
22℃-28℃			
> 28℃			