

Product specifications

Temperature measurement range: -20°C ~+60°C (-4°F~+140°F)
Temperature measurement accuracy: ±1°C (1.8°F)
Temperature resolution: 0.1
Humidity measurement range: 20%RH-99%RH
Humidity measurement accuracy: ±5%RH
Humidity resolution: 1%
Power supply: CR2032

Basic functions

- ◆ Temperature / Humidity display
- ◆ °C/°F temperature switch
- ◆ 24 Hours/All-time Max & Min Records
- ◆ Comfort indicator
- ◆ Backlit display
- ◆ Trend display



Operation method

①
②
③

◆Hold (①)key for 1.5 seconds to power on/off,click to open the backlight
◆Click (②)key to select the temperature unit:°C or °F
◆Click (③)key to select 24hrs/ALL TIME memory
◆Long press (③)key for 1.5 seconds to clear stored MAX/MIN data

Hang hole (max diameter 5mm)

Magnet inside to attach to any magnetic surface

Turn the cover to replace the battery

Open the stand ,the hygrometer can be stand on the table.

Comfort Indicator

Comfortable

Normal

Uncomfortable

Humidity \ Temperature	< 40%	40%-74%	> 74%
<22°C			
22°C-28°C			
> 28°C			