

# Digital temperature user manual

## PT-01

### Product specifications

Temperature measurement range:  $-20^{\circ}\text{C} \sim +60^{\circ}\text{C}$  ( $-4^{\circ}\text{F} \sim +140^{\circ}\text{F}$ )

Temperature measurement accuracy:  $\pm 1^{\circ}\text{C}$  ( $1.8^{\circ}\text{F}$ )

Temperature resolution: 0.1

Power supply: 3V CR2032  $\times$  1



### Basic functions

- ◆ Temperature display
- ◆  $^{\circ}\text{C}/^{\circ}\text{F}$  temperature switch
- ◆ Strong magnet
- ◆ Cleaning brush

### Operation method





(Button)

- ◆ Hold the button for 2 seconds to turn the power ON/OFF
- ◆ Double press the button to select the temperature unit:  $^{\circ}\text{C}$  or  $^{\circ}\text{F}$

To replace batteries:

Unscrew and slide out the battery compartment.



Caution: Prevents glass breakage.

1. Place parts on opposite sides of glass, offset from each other.
2. Slide them together slowly to attach.