

digital thermometer

instructions

Key function:

① key:

Click switch on / off, and press and hold for 2 seconds to convert $^{\circ}\text{C}$ / $^{\circ}\text{F}$

② key:

Click to turn on the backlight.

When the backlight is on, click the button to lock the current temperature

Press and hold for 2 seconds to display max temperature memory

Click again to display the Min temperature memory

Press and hold this interface for 2 seconds to clear the max / min value

Product parameters:

measuring range: -50°C – 300°C (-58.0°F – 572°F)

measurement error: $\pm 1^{\circ}\text{C}$

Measuring speed: 3s–5s

Battery model: CR2032

Resolution: 0.1°C / 0.1°F

