

Operating instruction

Features:

- LCD display.
- External sensing line design (length can be customized)
- Especially suitable for aquarium, indoor, pet box, freezer, etc.

Technical parameter:

- Sensor probe temperature range:-50°C~+110°C
- Using environment:
Temperature:5°C~+50°C Humidity:20%-80%
- Accuracy:±1°C
- Resolution:0.1
- Power: 1.5V LR44

Key:

- ON/OFF-Click Switch on/off.
- °C/°F-Click Celsius Fahrenheit to switch.

Instruction

- Open the battery cover, put the battery in correctly, and pay attention to the battery polarity.
- Display when put in the batteries. Pls take out the batteries when not use for long time.
- LCD display HHH when temperature is higher than 110°C
LCD display LLL when temperature is lower than -50°C

操作说明

特征:

- LCD显示器。
- 外置传感线设计(可定制长度)
- 特别适用于水族、室内、宠物箱、冷柜等。

技术参数:

- 传感器探头温度范围:-50°C~+110°C
- 使用环境: 温度:5°C~+50°C 湿度:20%-80%
- 精度:±1°C
- 分辨率:0.1
- 电源: 1.5V LR44

按键:

- ON/OFF-单击开关机。
- °C/°F-单击摄氏度华氏度切换。

指示:

- 打开电池盖,正确地放入电池,注意极性。
- 放入电池即显示。长时间不用时请拿出电池。
- 温度高于110°C时LCD显示HHH
温度低于-50°C时LCD显示LLL