

Digital temperature user manual

PT-01

Product specifications

Temperature measurement range: $-20^{\circ}\text{C} \sim +60^{\circ}\text{C}$ ($-4^{\circ}\text{F} \sim +140^{\circ}\text{F}$)

Temperature measurement accuracy: $\pm 1^{\circ}\text{C}$ (1.8°F)

Temperature resolution: 0.1

Power supply: 3V CR2032 $\times$ 1



Basic functions

- ◆ Temperature display
- ◆ $^{\circ}\text{C}/^{\circ}\text{F}$ temperature switch
- ◆ Strong magnet
- ◆ Cleaning brush

Operation method





(Button)

- ◇ Hold the button for 2 seconds to turn the power ON/OFF
- ◇ Double press the button to select the temperature unit: $^{\circ}\text{C}$ or $^{\circ}\text{F}$

To replace batteries:

Unscrew and slide out the battery compartment.



Caution: Prevents glass breakage.

1. Place parts on opposite sides of glass, offset from each other.
2. Slide them together slowly to attach.

温度计使用说明

PT-01

产品规格

温度测量范围: $-20^{\circ}\text{C} \sim +60^{\circ}\text{C}$ ($-4^{\circ}\text{F} \sim +140^{\circ}\text{F}$)

温度测量精度: $\pm 1^{\circ}\text{C}$ (1.8°F)

温度分辨率: 0.1

电源: 3V CR2032 纽扣电池 $\times 1$



基本功能

◆ 温度显示

◆ 强力磁吸

◆ $^{\circ}\text{C}/^{\circ}\text{F}$ 温度单位切换

◆ 双面清洁刷

操作方法





(按键)

◇ 长按按键2秒开/关机

◇ 双击按键切换温度显示单位: $^{\circ}\text{C}/^{\circ}\text{F}$

松开螺丝并取下电池仓以更换电池



注意!!!

1. 将两部分错开, 分别放在玻璃内外侧。
2. 缓慢滑动靠近直至吸合, 防止玻璃破碎。