

Features

- LCD display
- Insert design
- Simple appearance
- Two button batteries for longer use time
- Especially applied in refrigerator chiller deepfreeze etc.

Technical parameter

- Temperature range: $-20^{\circ}\text{C}\sim+110^{\circ}\text{C}$
- Using environment: Temperature: $-5^{\circ}\text{C}\sim+50^{\circ}\text{C}$

Humidity: $5\%\sim 80\%$

- Accuracy: $\pm 1^{\circ}\text{C}$ ($-30^{\circ}\text{C}\sim+40^{\circ}\text{C}$)
- Resolution: 1 ($\leq -20^{\circ}\text{C}$) 0.1 ($> -20^{\circ}\text{C}$)
- Power: two button battery (LR44, 1.5V)

Instruction

- Open the battery cover to put in two LR44 batteries
Correctly, pay attention to the polarity
- Display when put in the batteries. Pls take out the batteries when not use for long time
- LCD display H°C when temperature is higher than 110°C .
- LCD display L°C when temperature is lower than -20°C .
- Insert size: $48\times 28.6\text{mm}$