


Hygrometer user manual

Product diagram



Product specifications

1. Temperature measurement range: $-20^{\circ}\text{C} \sim 60^{\circ}\text{C}$ ($-4^{\circ}\text{F} \sim 140^{\circ}\text{F}$)
2. Temperature measurement accuracy: $\pm 1^{\circ}\text{C}$
3. Temperature resolution: 0.1
4. Power supply: 3V CR2032*1

Product functions

1. Mounting mode: Double Side Tape
2. Temperature display

产品手册

产品规格:

- 1.温度测量范围: $-20^{\circ}\text{C} \sim 60^{\circ}\text{C}$ ($-4^{\circ}\text{F} \sim 140^{\circ}\text{F}$)
- 2.温度测量精度: $\pm 1^{\circ}\text{C}$
- 3.温度分辨率: 0.1
- 4.电池: 3V CR2032纽扣电池

产品功能:

- 1.粘贴方式: 双面胶贴
- 2.测量温度

使用方法:

使用前清理干净粘贴处, 撕下温度计背胶膜, 粘贴于玻璃上, 按压温度计使双面胶更加贴合